

IPC Firmware Release Notes

Firmware version:

DH_IPC-HX5(4)XXX_Eng_N_Stream3_IVS_V2.420.0000.12.R.20151021

New features:

Null

Optimizations & bug fixes:

1. Fix the bug that ANR function would change camera resolution
2. Optimize image gain value